

ELECTRONIC BATCH CHARGERS

- Getting-over of all the mechanical limits
- Servo motor pusher driven
- Rotation angle and rotation sequence setting by keyboard
- More charging position (max 5 memorizable positions)
- Automatic loading control
- Batch quantity setup: independent setting of pusher stroke and velocity
- Remote machine setup from control panel in control room
- No mechanical intervention required for pusher stroke adjustment
- Possible integration in Batch charger control system of Hydramix
- Possible integration in Batch charger control system of Vibrating feeder
- Possible a dedicated solution in presence of Cullet Pre Heating



3 POSITION BATCH CHARGERS

- 3 different charging positions
- Minimum manual operations
- From the control panel it is possible to set the number of pulses of the pusher in one direction
- Less manual setup
- Pusher stroke: mechanical setting